



Switching on the new £50 Note



1. Whilst in the normal counting mode, press the **MENU** key. This takes you to the “Menu” screen.
2. Ensure ‘Options’ is highlighted and press the **ENTER** key. This takes you to the ‘Options’ screen.
3. Using the **NOTES**  key, select ‘Supervisor’ and press **ENTER**.
4. This takes you to the ‘PIN Number’ screen, press the following keys in the order shown below:



This takes you to the ‘Supervisor’ screen.

5. Ensure ‘Setup/Calibrate’ is highlighted and press **ENTER**.
6. Ensure ‘NOTES’ is highlighted and press **ENTER**.
You will now be in the screen entitled “Press **WRAP** for Setup”.
7. Highlight ‘£50N’, Press the **MENU** key to change the X to a ✓ .
8. With ‘£50N’ highlighted press the **ENTER** key.
9. Highlight ‘Band 1’, Press the **MENU** key to change the X to a ✓ .
10. With ‘Band 1’ highlighted press the **ENTER** key
11. Press the **MENU** key repeatedly to change ‘Notes/Band’ to 50.
12. Press the **NOTES** key to scroll to ‘-ve limit’ and again press the **MENU** key repeatedly to change to 0.52.
Scroll down again to ‘+ve limit’ and press the **MENU** key repeatedly to change to 0.52.
13. Press the **END** key twice to return to the ‘£50N ✓’ screen.
14. With ‘£50N’ highlighted press the **WRAP** key, and then press the **ENTER** key.
15. Tellermate will now ask you to put 10 loose Notes onto the Hod and press **ENTER**. Place 1 x £1 coin and 1 x 1p coin on to the Hod, then press **ENTER**. Then press the **ENTER** to complete calibration.
16. Press the **WRAP** key, until ‘Calibrate Band 1’ is displayed at the top of the screen and then press the **ENTER** key.
17. Place 5 empty £50 note bands onto the hod and press the **ENTER** key.
18. *Press END repeatedly to return normal counting mode.*

If you require assistance then please call the customer helpline on:

08707 87 70 87